




07H042.SA 115x 40,1x8,3

07H042.06 " " "

2



HONDA

900 ADVENTURER	95	•
900 THUNDERBIRD	95	•
800 VFR V-TEC ABS	02 > 05	•
1000 CBR XX	96	•


1000 VARADERO ABS	04	•
1000 XL VARADERO	99 > 03	•
1000 XL VARADERO (Linked Brake System)	00	•
1100 CB HORNET	99	•
1100 CB X-11	00	•

1100 CBR1100 XX	96	•
1100 ST	96	•
1300 STX PAN EUROPEAN	02	•
1800 GL GOLD WING	01	•
1800 VTX	01	•



07H043.SP 115x 40,1x 8,3

07H043.08 " " "



HONDA

650 NTV DEAUVILLE	03	•
700 NT DEAUVILLE ABS	06	•
800 VFR FI	98 > 01	•
800 VFR V-TEC ABS	02 > 05	•
800 VFR V-TEC ABS	06	•
1000 CBR XX	96	•

1000 VARADERO ABS	04	•
1000 XL VARADERO	99 > 03	•
1000 XL VARADERO (Linked Brake System)	00	•
1000 XLV VARADERO ABS	04	•
1000 XLV VARADERO TRAVEL ABS	04	•
1100 CB HORNET	99	•
1100 CB X-11	00	•

1100 CBR1100 XX	96	•
1100 ST	96	•
1300 STX PAN EUROPEAN	02	•
1300 VTX C	04	•
1800 GL GOLD WING	01	•
1800 VTX	01	•

